

Figure 7



## Web-based Log Books for Aircraft & Pilots!

305

# N123PG -- Log Entry Details

PlaneLog | Contact | Logout | aintraft page

506A

Aircraft:

N123PG

Administrative Data

Serial:

001450

Date:

December 5, 2000

Tach:

1401.00

Total Time:

1401.00

Date Entered:

December 5, 2000

**Entering User:** 

Client10 - Client 10

705

This entry has been modified 3 times

Entry Auth: A. Body

Auth Cert #:

123456789

Auth Cert:

A & P

The last modification was done for this reason:

Add Part Number

Modify Entry

709

### Entry:

Removed nosefork, serviced & install new washers.PN 1234. Adjust fork tension. Installnew o ring in primer, remove fuel selector, install new o-rings & lube reinstall. Ops check above ok A. Body A&P 123456789

533



# Figure 7A

Date Entered:

Entering User:

Modify Entry

This is an original entry



706

### Web-based Log Books for Aircraft & Pilots!

305

PlaneLog | Contact | Logout | aircraft page

Administrative Data

December 4, 2000

Client10 -- Client 10

#### N123PG -- Log Entry Details

Aircraft:

N123PG

Serial:

001450

Date:

December 4, 2000

Tach:

1200.00

**Total Time:** 

1200.00

Entry Auth: Auth Cert #:

Client 10 123546789

Private Pilot

Auth Cert:

506A

Entry:

C/W AD 78-23-01 by inspection and operation of fuel drain level door. Reoccurring inspection is due each 100 hrs. C/W AD 9526-13 by inspection of oil cooler hoses in accordance with AMOC #1, Hoses are airworthy at this time. C/W AD 90-02-23L by inspection of Prop hub for cracks. Reoccurring inspection due every 50 hours or every 50 flights, which ever comes first. Dressed and painted prop. C/W AD 76 07-12 by ops check of bendix mag switch. Reoccurring inspection is due each 100 hrs. Installed hardware on throttle control cable end at throttle and on fuel servo as illustrated in AD 80-14-02 and SB 537. Replaced bottom left engine vibration dampener. Resealed right and left main gear strut, serviced with fresh Hyd oil & nitrogen, Serviced nose strut with fluid & nitrogen. Resealed left brake wheel cylinder. Lubed landing gear. Cleaned and replaced all wheel bearings. Serviced tires with air pressure. Replaced wheel fairings studs and retainers as needed. Replaced left inboard sump valve. Zip tied loose wires for stall warning. Replaced vac regulator filter adjusted tension of control yoke cross over chain. Lubed all pulleys, hinges, rod ends, serviced fuel strainer. Installed missing strainer filte spring. Inspected ELT in accordance with FAR 91.207(d) Elt Battery is due June 1988. Washed lead from bottom of A/C. Serviced Battery & brake res. Ground run- ops normal. I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. A. Body 123456789 A/P

15

remaron.	<b>011</b> ← 201	
Web-based Log Books for A	ircraft & Pilots!	
305	\$	

NI23PG - Log Entry Modification

riginal Entry-----901

Date	Date Entered in System	Tack	Total Time	Eatry
December 5, 2000	<del>,</del>	1400.00	1400.00	Removed needork, serviced & install new weshers. Adjust fork tension, installnew oring in primer, remove fuel selector, install new orings & lube reinstall. Ope check above ok A. Body A&P 123456789

Log Eatry History ———902

Date	Date Entered In System	Tack	Total Time	Eatry	Reseas for Change
December 5, 2000		1400.00	1400.00	Removed nosefork, serviced & install now washers, Adjust fork tension. Installnew oring in primer, remove fuel selector, install now orings & tube reinstall. Ope check above ok A. Body A&P 123456789	Correct Total Time
December 5, 2000	-	1401.00	1401.00	Removed nosefork, serviced & install new washers. Adjust fork tension, installnew oring in primer, remove fuel selector, install new o-rings & lube prinstall. Ope check above ck. A. Body. A&P 123456789	Correct Total Time
December 5, 2000	-	1401.00	1401.00	Removed nosefork, serviced & install new weshest. Ph 1734. Alpit fork tension. Installnew of Anjine former, remove fuel selector, install new o-rings & tube reinstall. Ops check above ock A. Body A&P 123450789	Add Part Number

· · · · · · · · · · · · · · · · · · ·						
Modify Entry 903						
Authoriting User: Name: A. Box Client 10 cther>> Cert 4: [12165						
Repair Station:						
Work Order:	1					
Date Listed 16 NOT Actual Lag Eatry D (and due shown below); December 5, 1999 Month: Day: Year	Removed Bossfork, serviced & install new meshers:P8 1274. Adjust fork tansion. Installnew e ging in primer, remove fuel celector, install new e-ging & lube reinstall. Ope check shows ak A. Bedy As? 123434789					
Tach: [1681.66 No Tach Erry: Override Original Tachometer Adjustment TTAP:	! (use ITAF shown below): Yes No					
- bose some - Flight Pest STC Modifi	eration (non-sta)					

Modify previously entered Weight & Balance Data

